

Figure 1
Isolating Mixed Xylenes From Reformate




Figure 2
Generic Xylene Isomerization Process




Figure 3
Three Stage pX Crystallization Section




Figure 4
 Three-Stage Crystallization Ethylene Refrigeration Loop




Figure 5
Crystallization Section for Recovering pX From STDP Xylenes




Figure 6
Single Stage AAR Process

